August 2, 2016

Mr. Doug Lansing

Rainier Commons
918 S. Horton Street, Suite 101
Seattle, WA 98134

Re: **NVL Batch 1615609.00**

Project Name/Number: 2012-494

Project location: 3100 Airport Way S. Seattle, WA 98134

Dear Mr. Lansing,

Enclosed please find test results for samples submitted to our laboratory for analysis. Preparation and analysis of these samples were conducted in accordance with published industry standards and methods specified on the attached analytical report.

The content of this package consists of the following:

-Case Narrative & Definition of Data Qualifiers
-Analytical Test Results
-Applicable QC Summary
-Client Chain-of-Custody (CoC)
-NVL Receiving Record

The report is considered highly confidential and will not be released without your approval. Samples are archived for two weeks following analysis. Samples that are not retrieved by the client will be discarded after two weeks.

Thank you for using our laboratory services. If you need further assistance, please contact us at 206-547-0100 or 1-888-NVLLABS.

Sincerely,

Nick Ly, Technical Director

Enclosure: Sample Results

Case Narrative:

The following summarizes samples received on date as shown on the accompanied Chain of custody by NVL Laboratories, Inc. from Rainier Commons, LLC for Project number: 2012-494. Samples were logged in for PCB analysis per client request using both customer sample ID's and laboratory assigned ID's as listed on the Chain-of-Custody (CoC). All samples as received were processed and analyzed within specified turnaround time without any abnormalities and deviations that may affect the analytical results. All quality control requirements were acceptable unless stated otherwise. The conditions of all samples were acceptable at time of receipt and all samples submitted with this batch were analyzed unless stated otherwise on the CoC.

Test Results are reported in micrograms per cubic meter (ug/m^3) for PCB samples as shown on the analytical reports.

NVL Laboratories, Inc.
4708 Aurora Ave N, Seattle, WA 98103
p 206.547.0100 | f 206.634.1936 | www.nvllabs.com

Definition Appendix

Terms

% Rec	Percent recovery.
<	Below Reporting Limit(RL) or Limit of Quantitation(LoQ) of the instrument.
B	Blank contamination. The recorded results is associated with a contaminated blank.
DF	Dilution Factor
J	The reported concentration is an estimated value because something may be present in the sample that interfered with the analysis.
J1	The reported concentration is an estimated value because the laboratory control sample (LCS) is out of control limits.
J2	The reported concentration is an estimated value because the percent recovery for matrix spike is out of control limits.
J3	The reported concentration is an estimated value because the relative percent difference(RPD) for duplicate analysis is out of control limits.
J4	Percent recovery is outside of established control limits.
LCS	Laboratory Control Sample.
LFS	Laboratory Fortified Spike
Limits	The upper and lower control limits for spike recoveries.
LN	Quality control sample is outside of control limits. This analyte was not detected in the sample.
LOQ	Limit of quantitation(same as RL)
mg/kg	Milligrams per kilogram.
ND	Analyte not detected or below the reporting limit of the instrument or methodology

RCLLC 0009499

NVL Laboratories, Inc.
4708 Aurora Ave N, Seattle, WA 98103
p 206.547.0100 | f 206.634.1936 | www.nvllabs.com

Definition Appendix

Terms

PPM	Parts per Million.
QC Batch Group	Quality Control Batch Group. The entity that links analytical results and supporting quality control results.
R	The data are not reliable due to possible contamination or loss of material during preparation or analysis. Re-sampling and reanalysis are necessary for verification.
RL	Reporting Limit. The minimum concentration that can be quantified under routine operating conditions.
RPD	Relative Percent Difference. The relative difference between duplicate results(matrix spike, blank spike, or samples duplicate) expressed as a percentage.
RPD Limit	The maximum RPD allowed for a set of duplicate measurements(see RPD).
SMI	Surrogate has matrix interference.
Spike Conc.	The measured concentration, in sample basis units, of a spiked sample.
SURR-ND	Surrogate was not detected due to matrix interference or dilution.
ug/m3	Micrograms per cubic meter.
ug/mL	Micrograms per milliliter
ug	Microgram
ug/m3	microgram per cubic meter

ORGANICS LABORATORY SERVICES

NVL LABS

Company	Rainier Commons, LLC	**NVL Batch Number**	**1615609.00**
Address	918 S. Horton Street, Suite 101 Seattle, WA 98134	**TAT**	1 Day **AH** No
		Rush TAT	
Project Manager	Mr. Doug Lansing	**Due Date**	8/1/2016 **Time** 2:00 PM
Phone	(206) 447-0263	**Email**	lansinghomes@aol.com
Cell	(b) (6)	**Fax**	(206) 447-0299

Project Name/Number: 2012-494 **Project Location:** 3100 Airport Way S. Seattle, WA 98134

Subcategory Quantitative analysis

Item Code ORG-01 **Method** NIOSH 5503 PCB Aroclors <Air>

Total Number of Samples 1 Rush Samples

	Lab ID	Sample ID	Description	A/R
1	16248507	0729-16-2		A

	Print Name	Signature	Company	Date	Time
Sampled by	Client				
Relinquished by	Client				

Office Use Only	Print Name	Signature	Company	Date	Time
Received by	Justin Shearer		NVL	7/29/16	1400
Analyzed by	Shalini Patel		NVL	7-29-16	1700
Results Called by					
☐ **Faxed** ☐ **Emailed**					

Special Instructions:

Entered By: Justin Shearer Date: 7/29/2016 Time: 2:18 PM 1 of 1

NVL Laboratories, Inc.
4708 Aurora Ave N, Seattle, WA 98103
p 206.547.0100 | f 206.634.1936 | www.nvllabs.com

ANALYSIS REPORT
Polychlorinated Biphenyls in Air

Client	**Rainier Commons**	Samples Received*	**1**
SDG Number	**1615609.00**	Analyzed By	**Shalini Patel**
Date Reported	**08/02/2016**	Samples Analyzed*	**1**
Project Number	**2012-494**	Analysis Method	**5503**
Location	**3100 Airport Way S. Seattle, WA 98134**	Preparation Method	**5503PR**

* for this test only

Sample Number	**0729-16-2**	Received	07/29/2016
Lab Sample ID	16248507	Matrix	Air
Initial Sample Size	301 L	Units of Result	ug/m3

Analyte	RL	Final Result	Analysis Date
Aroclor-1016	0.13	< 0.13	07/29/2016
Aroclor-1221	0.13	< 0.13	07/29/2016
Aroclor-1232	0.13	< 0.13	07/29/2016
Aroclor-1242	0.13	< 0.13	07/29/2016
Aroclor-1248	0.13	< 0.13	07/29/2016
Aroclor-1254	0.13	< 0.13	07/29/2016
Aroclor-1260	0.13	< 0.13	07/29/2016
PCBs, Total	**0.13**	**<0.13**	**07/29/2016**

Comments: 15-200 WEST

NVL Laboratories, Inc.
4708 Aurora Ave N, Seattle, WA 98103
p 206.547.0100 | f 206.634.1936 | www.nvllabs.com

Quality Control Results

Project Number:	**2012-494**	**SDG Number:**	**1615609**
		Project Manager:	**Doug Lansing**
QC Batch(es):	**Q465**	Analysis Method:	**5503**
QC Batch Method:	5503PR	Analysis Description:	Polychlorinated Biphenyls in Air
Preparation Date:	07/29/2016		

Blank: BLK-1615609

Analyte	Blank Result	Units	DF	RL	Control Limit	Qualifiers
Aroclor-1016	ND	ug/m3	1	0.040	0.04	
Aroclor-1221	ND	ug/m3	1	0.040	0.04	
Aroclor-1232	ND	ug/m3	1	0.040	0.04	
Aroclor-1242	ND	ug/m3	1	0.040	0.04	
Aroclor-1248	ND	ug/m3	1	0.040	0.04	
Aroclor-1254	ND	ug/m3	1	0.040	0.04	
Aroclor-1260	ND	ug/m3	1	0.040	0.04	
PCBs, Total	ND	ug/m3	1	0.040	0.04	
Surrogates:				% Rec		
Tetrachloro-m-xylene			1	113	40-140	
Decachlorobiphenyl			1	114	40-140	

Lab Control Sample: LCS-1254-1615609

Analyte	Blank Spike Result	Units	DF	Spike Conc.	% Rec	% Rec Limits	Qualifiers
Aroclor-1254	178	ug/m3	1	200	89	40-140	
Surrogates:							
Tetrachloro-m-xylene			1		97	40-140	
Decachlorobiphenyl			1		104	40-140	

Lab Control Sample: LCS-1016+1260-1615609
Lab Control Sample Duplicate: LCS Dup-1016+1260

Analyte	Blank Spike Result	Units	DF	Spike Conc.	% Rec	Limits	RPD	RPD Limit	Qualifiers
Aroclor-1016	184	ug/m3	1	200	92	40-140			
	224			200	112	40-140	20	50	
Aroclor-1260	184	ug/m3	1	200	92	40-140			
	184			200	92	40-140	0	50	
Surrogates:									
Tetrachloro-m-xylene			1		109	40-140			
					112	40-140			
Decachlorobiphenyl			1		112	40-140			
					115	40-140			

NVL Laboratories, Inc.
4708 Aurora Ave N, Seattle, WA 98103
p 206.547.0100 | f 206.634.1936 | www.nvllabs.com

Surrogate Recovery Summary Report

Client Rainier Commons **SDG Number** 1615609

Project 2012-494

Customer Sample ID	Lab Sample ID	Analyte	Recovery	Limits
0729-16-2	16248507	Decachlorobiphenyl	114%	40-140
0729-16-2	16248507	Tetrachloro-m-xylene	102%	40-140
BLK-1615609	BLK-1615609	Decachlorobiphenyl	114%	40-140
BLK-1615609	BLK-1615609	Tetrachloro-m-xylene	113%	40-140
LCS Dup-1016+1260	LCS Dup-1016+1260	Decachlorobiphenyl	115%	40-140
LCS Dup-1016+1260	LCS Dup-1016+1260	Tetrachloro-m-xylene	112%	40-140
LCS-1016+1260-1615609	LCS-1016+1260-1615609	Decachlorobiphenyl	112%	40-140
LCS-1016+1260-1615609	LCS-1016+1260-1615609	Tetrachloro-m-xylene	109%	40-140
LCS-1254-1615609	LCS-1254-1615609	Decachlorobiphenyl	104%	40-140
LCS-1254-1615609	LCS-1254-1615609	Tetrachloro-m-xylene	97%	40-140

* Recovery outside limits

NVL Laboratories, Inc.
4708 Aurora Ave N, Seattle, WA 98103
p 206.547.0100 | f 206.634.1936 | www.nvllabs.com

INITIAL AND CONTINUING CALIBRATION VERIFICATION

SDG No: **1615609** Contract: **N/A**

Determination: **5503 PCB Aroclors <Air>**

Run	Sample	Source	Analyzed	Analyte	True	Found	Unit	% Rec	Limits
R000458	CCV1-1016-1260	PCB_2016-1-10	07/29/2016	Aroclor-1016	0.1	0.102	ug/mL	102	80-120
		PCB_2016-1-10	07/29/2016	Aroclor-1260	0.1	0.099	ug/mL	99	80-120
	CCV1-1254	PCB_2016-1-11	07/29/2016	Aroclor-1254	0.1	0.102	ug/mL	102	80-120
	ICV 1016-1254-1260	PCB_2016-1-15	07/29/2016	Aroclor-1016	0.1	0.087	ug/mL	87	85-115
		PCB_2016-1-15	07/29/2016	Aroclor-1254	0.1	0.091	ug/mL	91	85-115
		PCB_2016-1-15	07/29/2016	Aroclor-1260	0.1	0.085	ug/mL	85	85-115
	CCV 2-1016-1260	PCB_2016-1-10	07/29/2016	Aroclor-1016	0.1	0.102	ug/mL	102	80-120
		PCB_2016-1-10	07/29/2016	Aroclor-1260	0.1	0.102	ug/mL	102	80-120
	CCV2-1254	PCB_2016-1-11	07/29/2016	Aroclor-1254	0.1	0.102	ug/mL	102	80-120

% Rec = Percent recovery

* = Percent recovery not within control limits

NVL Laboratories, Inc.

4708 Aurora Ave N, Seattle, WA 98103
Tel: 206.547.0100 Emerg.Cell: 206.914.4646
Fax: 206.634.1936 1.888.NVL.LABS (685.5227)

CHAIN of CUSTODY SAMPLE LOG

1615609

Client Rainier Commons, LLC
Street 918 S. Horton Street, Suite 101
Seattle, WA 98134

Project Manager Mr. Doug Lansing
Project Location 3100 Airport Way S. Seattle,WA 98134

Phone: (206) 447-0263 **Fax:** (206) 447-0299

NVL Batch Number
Client Job Number 2012-494
Total Samples ONE
Turn Around Time ☐ 1-Hr ☐ 2-Hrs ☐ 4-Hrs ☐ 8-Hrs ☐ 12-Hrs ☒ 24-Hrs ☐ 2 Days ☐ 3 Days ☐ 4 Days ☐ 5 Days ☐ 6-10 Days
Please call for TAT less than 24 Hrs

Email address lansinghomes@aol.com
Cell (b) (6)

☐ Asbestos Air	☐ PCM (NIOSH 7400)	☐ TEM (NIOSH 7402)	☐ TEM (AHERA)	☐ TEM (EPA Level II)	☐ Other	
☐ Asbestos Bulk	☐ PLM (EPA/600/R-93/116)	☐ PLM (EPA Point Count)	☐ PLM (EPA Gravimetry)	☐ TEM BULK		
☐ Mold/Fungus	☐ Mold Air	☐ Mold Bulk	☐ Rotometer Calibration			

METALS	Det. Limit	Matrix		RCRA Metals		Other Metals
☐ Total Metals	☐ FAA (ppm	☐ Air Filter	☐ Soil	☐ Arsenic (As)	☐ All 8	☐ All 3
☐ TCLP	☐ ICP (ppm)	☐ Drinking water	☐ Paint Chips in %	☐ Barium (Ba)	☐ Chromium (Cr	☐ Copper (Cu)
☐ Cr 6	☐ GFAA (ppl	☐ Dust/wipe (Area)	☐ Paint Chips in cm	☐ Cadmium (Cd)	☐ Lead (Pb)	☐ Nickel (Ni)
					☐ Mercury (Hg)	☐ Zinc (Zn)

☒ Other Types of Analysis ☐ Fiberglass ☐ Nuisance Dust ☒ Other (Specify) PCB - AIR
☐ Silica ☐ Respirable Dust

Condition of Package: ☐ Good ☐ Damaged (no spillage) ☐ Severe damage (spillage)

Seq. #	Lab ID	Client Sample Number	Comments (e.g Sample are, Sample Volume, etc)	A/R
1		0729-16-2	15-200 WEST	
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				

	Print Below	Sign Below	Company	Date	Time
Sampled by	D LANSING		RAINIER	7/29/16	1130
Relinquished by	DAVE LEONARD		NVL	7/29/16	1300
Received by	J. SHEAR		NVL	7-29-16	1400
Analyzed by	Shalini Patel		NVL	7-29-16	1700
Results Called by					
Results Faxed by					

Special Instructions: Unless requested in writing, all samples will be disposed of two (2) weeks after analysis.

RCLLC 0009506

1615609

#2

Rainier Commons Exterior Paint Removal Project

Air Sample Data Sheet

(Note Date, Report # and Page #on each sheet)

Date 07-29-16 Daily Report #: PHASE II

Sample ID	0729-16-2
Contaminant	PCB
Sample Location Description	Loc # 2
Sample Inside/Outside?	I
Start Flow Rate	1.0
End Flow Rate	1.0
Start Time	05:47
End Time	10:48
Total Time	
Total Volume	
Notes -Including adjacent activities	15-200 WEST

SAMPLER

Signature

7-29-16
Date